

TO ALL FLEET VESSELS

Ref: DMA-SAPID/AIFI01/00/C1134

Date: 2021.06.21

In The Name Of God

Dear Captain
Good Day,

Pl's find attached file "NEAR MISS & FLEET CASUALTY 1ST.QUARTER 1400"
for your kind attention and necessary precaution measures.

You are requested to confirm receipt, discuss the contents in the next
consolidated meeting on board & keep a copy in the file DA-11 .

BEST REGARDS

CAPT.A.Momeni.N.

Accident Investigation And Fleet Inspection

Department Of Maritime Affairs

Sapid Shipping Co.

Tel:+98-21-2610 0357

Fax:+98-21-2610 0356

Direct Tel:+98-21-2384 3551

PL'S REPLY TO; dma@sapidshpg.com
cso@sapidshpg.com



SAPID SHIPPING co.
Global service, Global Partnership

CONFIDENTIALITY NOTICE

This email is intended only for the addressee named above. As this email may contain confidential or privileged information, if you are not the named addressee or the person responsible for delivering the message to the named addressee, Please inform us (By Email or Telephone) before deleting it. Please delete the document from your E-Mail system. The contents should not be disclosed to any other person nor copies taken.

FLEET CASUALTIES

<i>VESSEL'S NAME</i>	<i>SM</i>	<i>COMPANY</i>	<i>DATE</i>	<i>VOYAGE NUMBER</i>	<i>PLACE</i>	<i>NAME OF MASTER</i>	<i>CODE</i>	<i>Category</i>
ARTARIA	3	SAPID	15/2/2021	ODD-0009	China to Iran	CAPT.M.FIROOZI	13.8	1
WARTA	2	SAPID	2021.03.24	S6-2301	B.I.K	MEHDI DARVISHNARENJBON	13.8	1
WARTA	2	SAPID	2021.03.24	S6-2301	B.I.K	CAPT.M.DARVISH.N	6.2	1
DELICE	6	SAPID	31.03.2021	S7-0257-D3	KAZ OPL	CAPT.A.R.MOAREFIAN	6.4	2
OURA	2	SAPID	06.04.2021	S6-2296	BEDIBUNDER ANCHORAGE	CAPT.F.EBRAHIMI	6.2	1
NEGAR	1	SAPID	2021.04.18	SCY-1098	YANGON TO P.KLANG	M.YAGHOUBI	13.7	1
JAIRAN	1	SAPID	19.04.2021	S4-2614	BND ANCHOR	M.NABIZADEH SH	13.8	1
ARSHAM	2	SAPID	19.04.2021	S6-2306	MAGDALLA ANCHORAGE	H.DELBARY	13.8	1
ARTMAN	2	SAPID	24.04.2021	S6_2283	AB	SDH.NODEHI	13.8	1

FLEET CASUALTIES

MIAMAPRIDE	2	SAPID	25.04.20	s6-2316	B.ABBAS	E.KHOJASTEHEJAD	13.8	1
AMINA	3	SAPID	01/5/2021	S6-2308	SHUAYBAH	A.ARMANDEI	13.7	1
ELYANA	1	SAPID	25.04.2021	s4-2613	Cigading	Sh.sharifi	6.3	2
SAVIZ	1	SAPID		S4-2099	AT SEA	M. Vasheghani Farahani	6.1	2
BASKAR	2	SAPID	01.05.2021	S6-2309	MAGDALLA / INDIA	MAHDI SOLEIMANI	6.3	2
ELYANA	1	SAPID	26.04.2021	S4-2613	Cigading	Sh.Sharifi	6.3	2
BASKAR	2	SAPID	01.05.2021	S6-2309	Magdalla anch	MAHDI SOLEIMANI	6.3	2

FLEET CASUALTIES

BASKAR	2	SAPID	01.05.2021	S6-2309	MAGDALLA / INDIA	MAHDI SOLEIMANI	6.3	2
PARISAN	2	SAPID	02.05.2021	S6-2322	SONGKHLA // THAILAND	M.KHAJEHGIRI	6.3	2
BASKAR	2	SAPID	04.05.2021	S6-2309	MAGDALLA ANCHORAGE	MAHDI SOLEIMANI	6.3	2
AYSAN	1	SAPID	5.12.2021	S4-2618	SHUAIBAH	A.R.KARIMI	6.3	2
BAVAND	2	SAPID	09.05.2021	S6-2303	ZHENJIANG	F.RABIE	6.3	2
BAVAND	2	SAPID	10.05.2021	S6-2303	ZHENJIANG	F.RABIE	6.3	2
BAVAND	2	SAPID	11.05.2021	S6-2303	ZHENJIANG	F.RABIE	6.3	2
PARNIA	1	SAPID	13.05.2021	XPG-1679	Asaluyeh to B.ABBAS	YASIN DERIS	13.7	1
ARDAVAN	2	SAPID	10.05.2021	S6-2325	B.ABBAS	M.MOTALEI	13.7	1
AYSAN	1	SAPID	2021.05.15	S4-2618	SHUAIBAH ANCHORAGE	ALIREZA KARIMI	13.7	1

FLEET CASUALTIES

BAVAND	2	SAPID	25.05.2021	S6-2303	ZHENJIANG To VIZAG	F.RABIE	13.7	1
AYSAN	1	SAPID	12.05.2021	S4-2618	SHUAIBAH	A.R.KARIMI	6.3	2
ARTARIA	3	SAPID	14.05.2021	S6-2329	B.Abbas	Mohammad Firoozi	6.3	2
NEGAR	1	SAPID	19.05.2021	scy-1101	port klang north port	m.yaghoubi.k	6.3	2
ELYANA	1	SAPID	21.05.2021	S4-2616	BIK	SH.SHARIFI	6.3	2
ELYANA	1	SAPID	21.05.2021	S4-2616	BIK	SH.SHARIFI	6.3	2
BEHDOKHT	2	SAPID	22.05.2021	S1-0163	B.ABBAS	B.ESMAILIAN	6.3	2
BASKAR	2	SAPID	23.05.2021	S6-2327	B.ABBAS	MEHDI SOLEYMANI	6.3	2
BAHJAT	2	SAPID	23.05.2021	S6-2319	MAGDALLA ANCHORAGE	CH.BARZEGARI	6.3	2
BAHJAT	2	SAPID	26.05.2021	S6-2319	MAGDALLA ANCHORAGE	Capt.CH.Barzegaei	6.3	2
BAHJAT	2	SAPID	27.05.2021	S6-2319	MAGDALLA ANCHORAGE	CH.Barzegari	6.3	2

FLEET CASUALTIES

BRIEF DESCRIPTION	CARE GORY	<i>Reported MD</i>
He slipped fell and down during Rough sea and vl heavy rolling while at work in galley,pain and bulge symptom.(MAHDI NASRABADI)	LSI	
During Working on Expansion joint of Ballast line DB NO1 STBD Side while tightening the bolt & nut the wrench hit to the down side the mentum of Mr.ASHKAN JABERANSARI (CARPENTER) & cause small gash on his skin .(ASHKAN JABERANSARI)	LSI	
You Are Hereby Notified That, At 16:00 Lt On 24.03.2021 At B.I.K, During Loading Of Cargo Hold No.4 By Crane No.4 With Full Loaded Shore Grab ,Accommodation Ladder Sitting Beam Impact By Grab & Deformed And Can Not Hold Accommodation Ladder Secured In It 'sPosition For voyage.	SC	
1-station: 60 meter - outer dimension: 50 mm - / 2-R_bar: 50 meter – dimension: 23 mm 3-flat bar: 19 pcs (dimension: height:103 cm width:63 mm thickness: 16 mm) 4-Support flat bar: 6 pcs (dimension: height:61 cm width:63 mm thickness: 16 mm) 5-Fish plate: length: 30 meter height:23.5 cm thickness:10 mm / 6-Hose guard: length: 16 meter outer dimation:35 cm 7-hose guard bracket: 11 pcs (dimention: height: 77 cm width:26 cm angle bar:71 mm thickness:10 mm)8- support pipe for hose guard bracket: 12 mtr dimension:50 mm 9-pilot station door and fwd life raft door: stanchion: 250 cm outer dimation: 95 mm + 4 hinge +R-bar 250 cm d:23 mm 10-full extend of damage will be ascertain after detail inspection.	SC	
ON 06.04.2021 AT 1315 HRS LT WHILE DISCHARGING BULK CLINKER TWO VERTICAL SECURING ANGLE BAR AND STANDING PLATE OF STBD ACC. LADDER DEFORMED BY HITTING OF FALLEN SHIP'S GRAB.IN ADDITION ABOVE THE GAURD RAIL AND SUPPORTING STANCHIONS OF PILOT EMBARKATION POINT ON STBD SIDE NEAR ACC. LADDER BROKEN & DISMANTLED	SC	
On 2021.04.17 after completion of welding on deck while ship's welder wanted to form the malleable welded metal removed his welding maskshield and tried to forming the malleable weld that one small chip of weld hurled into his left eye and hurts to his left eye iris of the eye.(MOHAMMAD MOFIDI)	SI	
ON 11.04.2021 WHEN BOSUN ENGAGED IN UNCOILING NEW WIRE OF CRANE, SUDDENLY TIMBLE OF WIRE RELEASED AND HIT HIS RIGHT SHANK AND ULCERATE HIS LEG.AFTER FEW DAYS HE FEEL PAIN IN HIS RIGHT KNEE.AFTER TREATMENT ON BOARD STILL PAIN EXIST.TO BE VISITED BY DOCTOR FOR FUTHER TREATMENT.	LSI	
On 19.04.2021@05:15 during cargo operation stabilizer wire for crane hold no 3 twisted & cargo operation stopped. Cargo supervisor asked to rectify the problem and resume cargo operation. Dutyofficer and 2 AB proceed to rectify the problem. Duty officer and AB's wear PPE. Duty officer askedAB to close hold no 3 for more safety . After open the stabilizer wire AB suddenly lost his balance and fell down on his back side from the hatch coaming to main deck. He was feeling pain, and then duty officer and chief officer and the other crew transfered him to his cabin with stretcher.	LSI	
ON 23/04/2021 @14:00 WHILE ABOVE MENTIONED PERSON WORKING WITH HIGHPRESSURE DE_SCALING MACHINE SUDDENLY PASSING OF HIGHPRESSURE HOSE THROUGH HIS SAFETY SHOES CAUSED MINOR WOUND IN HIS LEG.	LSI	

FLEET CASUALTIES

During berthing operation on 24.04.2021 when aft tug approaching for pass the aft station tug line, messenger line was broken due to weakness of tug messenger line, and aft personal tried to heave up the tug line with using their hand and caused result 2nd officer mohammad rahdari found backache due to excessive load on his back.	LSI	
As the O.S (Nima Jahanshiri) instructed to signal crane operator for discharging cargo from port side of the cargo hold. The mentioned person stays on the grating plate near hatch operating joy stick and completed his task, then he jumped from grating plate on deck instead of using ladder. Approximate height of 1.10 mtr. This caused extreme pressure over his leg and after few minutes he felt severe pain on his left testicle	SI	
While vessel was engaged discharging operation on 25.04.2021 at 0200 crane operator mishandling caused damage to stanchion near hatch 3 starboard side.	SC	
This is to inform that, on 06/04/2021 at 05.52' Am (Lmt), Port Side Aft of Vessel vibrated very strongly, E/R Alarms activated & Black-Out take place, hence going to port side aft rashly & observed smoke & explosive gas around of mentioned area, after that going to E/R immediately & found sea-water coming in E/R & sea water level increased to generator alternator & big value of seawater splash to first floor of E/R with height of 4.0 meter, during this time No.3 A/E is running. Therefore, stopped generator from C/R & quickly action taken & closed all quick closing valves, water tight door, air bottle starting valves, fan-flaps/funnel & etc. Furthermore, sea-water level in E/R increased to first floor & all of E/R machinery flooded inside of sea-water & sea-water level increased to water line of ship's then sea-water level coming to constant & trim increased from 2.5 meter to 6.8 meter & calculated around 6000 tone sea-water goes in E/R. With noted that, taken sounding measurement from all H.O I D.O & water ballast tanks & found D.O storage tanks (P & S) sides from nil increased level to 80 cm, then inspected inside of all hatches & seen No.5 hatch, sea-water corning inside slightly & all of mentioned sounding level not changing. As per may investigation regarding extent of damage & flooded all of machinery 28 days inside of sea-water & present sea-water mixed with dirty oil I D.O /Sludge, we can estimate all of electrical equipment damaged completely. Because explosion occurred inside of E/R & cause created two big holes, each around 2x3 meters between engine frame No's 20 to 27 & damaged shell plating, removed from foundation ows, G.S P/P, 1-1.0 transfer P/P & also damaged all of overboard valves, removed M/E crankcase doors, For your kind perusal most of machineries in port side bottom floor of E/R unacceptable to use in future.	MD	
On 01.05.2021 at 20:00 LT while v/l was at Magdalla anchorage during cargo operation following location have been damaged. 1- on abreast of cargo hold no 2 port side, standing platform stanchion & railing pipe dia 46 mm, length 3 meter, plate bar dia: 25 mm 3 meter, rectangular plate 3 meter breadth: 7 cm * 20 mm thickness	MD	
While vessel at cigading port, during discharging of steel billets due to bad operation of crane and lift truck operator steel billet touch the ship's hull (fram no 55-70-90) and scratched the ship's hull paint	LSC	
On 01.05.2021 at 2300 LT while v/l was at Magdalla anchorage during cargo operation following location have been damaged. 1- railing around australian ladder aft part of hold no 2 damaged & broken at one point, pipe dia: 33 mm, L: 1 meter, plate bar 20 mm dia & length 1 meter	MD	

FLEET CASUALTIES

On 01.05.2021 at 09:30 LT while v/l was at Magdalla anchorage during cargo operation following location have been damaged. 1- on abreast of hold no4, stbd side, railing (pipe dia 46 mm, L:1 m) & plate bar L:1M dia:25 mm 2- on abreast of hold no4, stbd side, railing (pipe dia 46 mm, L:2 m) & plate bar L:2 M dia:25 mm 3- on abreast of hold no4, stbd side, railing (pipe dia 46 mm, L:5 m) & plate bar L:5 M dia:25 mm 4- on abreast of hold no4, stbd side, railing (pipe dia 46 mm, L:1 m) & plate bar L:1 M dia:25 mm 5- on abreast of hold no4, stbd side, supporting stanchion (plate L:2 m* breadth 7cm *thickness 20 mm	MD	
PAON 02.05.2021 DURING LOADING OF MDF IN BUNDLE BY SHIP'S CRANE, OBSERVED THAT THE CRANE OPERATOR DAMAGED TO DECK GUARD RAIL AND BROKE TWO GUARD RAILS	SC	
ON 04.05.2021 at 09:00 LT while v/l was at Magdalla anchorage during cargo operation following location have been damaged: 1- On abreast of cargo hold no 3 stbd side railing(pipe dia 46 mm, length: 1.5 mtr) plate bar length :1.5 meter & dia:25 mm 2- On abreast of cargo hold no 3 stbd side railing(pipe dia 46 mm, length: 1.5 mtr plate bar length :1.5 meter & dia:25 mm	SC	
□ On 12.05.2021 while wessel wast shuaibah port at 1230 Discharging operation commence after DELIVERY of ships crane to stevedore confirming their normal operation at 1305 lt while discharging operation in progress due to mishandling & bad operation of crane operation crane no. 3 the hoisting wire twisted around hoisting wire drum and caused to damaged to hoisting wire.	MD	
While Stevedors were engaged on discharging cargo from hold no 2 by ships crane no 2 . On 09.05.2021 at 2113 hrs ne horizontal hand rail on fwd of hold no.3 (stbd side) broken and dented. Damage including : pire dia= 45 mm l=1500mm	MD	
While Stevedors were engaged on discharging cargo from hold no 4 by ships crane no 3 . On 10.05.2021 at 0310 one horizontal hand rail next to hatch no 4 STBD side fwd part denred. Damage inoludes; PIRE DIA=45mm L=1500mm ROD DIA=20mm L=1500mm	MD	
Wile stevedores were engaged on discharging cargo from following hols on: 11.05.2021 at 2120 two horizontal & vertical hand rail between hatch no 2&3. (STBD side) fwd part dented & broken and also two horizontal & vertical hand rail fwd of hatch no 4 (STBD side) fwd part dented. Damage includes PIPE DIA=45mm L=4000mm ROD DIA=20mm L=4800mm VERTical Stanchion +l2040mm Wide=80mm THICKNESS=20mm	MD	
During normal job washing the last station using fresh water hose while tightening the hose clamps the screw driver accidentally plunged deeply in to palm of his left hand.(ehsan safdari)	SI	
DURING SHIFTING OF STABILIZER WIRE , WIRE IMPACTED TO HIS FINGER AND FINGER INJERD (NOT CUT FORTUNATELY)BY PRESSURE OF WIRE ON FINGER AND PLATE(AFSHIN ASHOURI)	SI	
On 15.05.2021 At 0930 lt , while vsl at SHUAIBAH ANCHORAGE during adjusting crane's wire on hoisting drum inside of crane no.3 mast , ch/off informed bridge that bosun's finger has been trapped under the crane's wire around hoisting drum, caused his finger injury and the nail broken .(RASOUL BAHADORI)	SI	


FLEET CASUALTIES

While he was entering the eng room through the aft entrance, due to structural design of plating next to the ladder step, he could not put his foot firmly on the first step due to vsl slight rolling, caused to slip and fell down on the same plating by his buttock which then felt sever pain on his lower back bone.(AMIN BEHZAD)	SI	
ON 12.05.2021 WHILE VESSEL WAS AT SHUAIBAH PORT AT 1230 DISCHARGING OPERATION COMMENCE AFTER DELIVERY OF SHIP'S CRANE TO STEVEDORE CONFIRMING THEIR NORMAL OPERATION AT 1305 LT WHILE DISCHARGING OPERATION IN PROGRESS DUE TO MISHANDLING & BAD OPERATION OF CRANE OPERATOR CRANE NO. 3 THE HOISTING WIRE TWISTED AROUND HOISTING WIRE DRUM. AND CAUSED TO BE DAMAGED TO HOISTING WIRE.	MD	
The crane no.1 hoisting motor hydraulic pump seal damaged by the operator on 13.05.2021 during Rough / mishandling and inconvenient operation despite of several verbal warnings to the crane operator by duty officer.	MD	
on 19.05.2021 at port kland north port ,during loading container while gantry operator was trying to load 20' feet container on cross deck between hold no.4&5 stbd side he made mistake in his container position adjusting and container was slip and cause to damage to stanchion of natural ventilator	MD	
While vsl was engaged in an operation of loading of steel slab at BIK port on 2021.05.20 following damage occurred: glass of crane NO 1 broken	MD	
While vessel was engaged in an operation of loading of steel slab at BIK port at 21.05.2021 due to mishandling of crane operator following damage occurred; Buckles: frame No; 131-110-151 Scratch: 150-124-58	MD	
During discharging of cargo it observed that pay loader damaged straight ladder cargo hold no.3 the ladder fully damaged & crushed about 1 mtr	MD	
On 23.05.2021 at 08:30 LT while v/l was at B.ABBAS PORT during cargo operation following location have been damaged: crane no 2 , grab's electrical cable damaged , insulation & electrical damaged	MD	
Kindly note on 24.05.2021, while discharging cargo (GYPSUM IN BULK) at MAGDALLA anchorage by ship's crane and grab's due to negligence of crane operator, the grab hits on cargo hold inspection platform and damage the platform , please arrange competent work shop to rectify the damaged item's as original Material require to rectify defect as follows: steel plate 15 mm, dimension 110 cm x 7 cm, 1 pcs // - steel pipe O.D: 42 mm, length: 120 cm, 1 pcs with one 90 degree bend // Steel round 20 mm, length: 120 cm, 2 pcs , with one 90 degree bend / steel equal angle 60x60x5 mm , 50 cm , 2 pcs	MD	
Kindly note on 26.05.2021, while discharging cargo (GYPSUM IN BULK) at MAGDALLA anchorage by ship's crane and grab's , the ship's side guard railing damaged by barge rope in port side of cargo hold no.3 , 2 please arrange competent work shop to rectify the damaged item's as original The deformed and defective parts to be crop and new one to be fabricated and welded in place as original Material require to rectify defect as follows: steel plate 15 mm, dimension 80 cm x 7 cm, 1 pcs // - steel plate 15 mm, dimension 25 cm x 7 cm, 3 pcs - steel pipe O.D: 47 mm, length: 120 cm, 1 pcs // Steel round 20 mm, length: 120 cm, 2 pcs.	MD	
Kindly note on 27.05.2021, while discharging cargo (GYPSUM IN BULK) at MAGDALLA anchorage by ship's crane and grab's following damage by discharge gang A) the ship's side guard railing damaged starboard side of cargo hold no.1 The deformed and defective parts to be crop and new one to be fabricated and welded in place as original Material require to rectify defect as follows : - steel plate 15 mm, dimension 30 cm x 7 cm, 1 pcs - steel pipe O.D: 47 mm, length: 150 cm, 1 pcs	MD	

FLEET CASUALTIES


<p>Kindly note on 30.05.2021, while discharging cargo (GYPSUM IN BULK) at MAGDALLA anchorage byhip's crane and grab's, GRAB NO.1 BUCKET damaged by discharge gang (stevedoring)Grab no.1 bucket plate torn in two place and plating buckled(The bucket almost out of use and to be renewedSpecification of grab and bucketType of grab: Electro Hydraulic Clamshell BucketDrawing: bucket (A) assembly, pos.: 001, description: bucket, part nr.10649.2001</p>	<p>MD</p>	
<p>While he was entering the eng room through the aft entrance, due to structural design of plating next to the ladder step, he could not put his foot firmly on the first step due to vsI slight rolling, caused to slip and fell down on the same plating by his buttock which then felt sever pain on his lower back bone</p>	<p>SI</p>	
<p>On date 08.06.2021 during repair of main engine (changing of upper jacket), due to importance of the job/ emergency case and condition while vessel was at sea (sea condition moderate sea: vessel rolling slightly), 3rd engineer permitted to made fast the removing upper jacket for preventing more unwanted movements, due to rolling of the ship, the cylinder head suddenly moved violently towards him and touched his body. After a few minutes he was feeling strong pain at the touched area (right hand of chest from fourth rib toward down) so cause difficulty to resume his duty. Herby request to visit and check by special physician.</p>	<p>SI</p>	
<p>On 2021/05/29 at 10:30 while vessel was at MAGDALLA anchorage area for discharge of cargo (gypsum in bulk),Buson and other deck crew were engaged to park the grab of crane no. 4 in her place . due to heavy s well in anchorage area and v/l rolling,suddenly grab moved ,cause of gently rolling ,so Buson left hand finger Pressed. Between the body of grab and hatch coming. Unfortunately the first knuckle of his finger scratched</p>	<p>LSI</p>	
<p>On 15.06.2021 at 1400 It during rescue boat drill, when Bosun trying to restore the embarkation ladder with other crew , his right ankle twisted and causing severe pain on his leg.</p>	<p>SI</p>	

<i>CATEGORY</i>	<i>CODE</i>	<i>NUMBER OF ACCIDENTS</i>	<i>PERCENTAGE OF TOTAL</i>
<i>CREW ERROR</i>	<i>1</i>	<i>18</i>	<i>42.86</i>
<i>3RD PARTY ERROR</i>	<i>2</i>	<i>24</i>	<i>57.14</i>
<i>MECHANICAL FAILURE</i>	<i>3</i>	<i>0</i>	<i>0.00</i>
<i>ACT OF GOD</i>	<i>4</i>	<i>0</i>	<i>0.00</i>
<i>TOTAL</i>		<i>42</i>	





ACT OF GOD

○



DESCRIPTION	ACCIDENT CODE	NUMBER OF OCCURRANCES	PERCENTAGE OF TOTAL
<i>COLLISION WITH OTHER VESSEL</i>	1	0	0.00
<i>CONTACT DAMAGE WITH DOCK</i>	2.1	0	0.00
<i>CONTACT DAMAGE WITH FLOATING OR SUBMERGED OBJECT/ICEBERG</i>	2.2	0	0.00
<i>CONTACT DAMAGE WITH BUOY</i>	2.3	0	0.00
<i>CONTACT DAMAGE WITH FISHING GEAR</i>	2.4	0	0.00
<i>GROUNDING</i>	3	0	0.00
<i>FIRE</i>	4	0	0.00
<i>HEAVY WEATHER DAMAGE</i>	5	0	0.00
<i>DAMAGE TO HULL/MACHINERY/CARGO GEAR DUE TO WEAR & TEAR/UNKNOWN REASON</i>	6.1	1	2.44
<i>DAMAGE TO HULL/MACHINERY/CARGO GEAR DUE TO CREW NEGLIGENCE</i>	6.2	2	4.88
<i>DAMAGE TO HULL/MACHINERY/CARGO GEAR DUE TO STEVEDORE NEGLIGENCE</i>	6.3	21	51.22
<i>DAMAGE TO HULL/MACHINERY/CARGO GEAR DUE TO NEGLIGENCE OF 3RD PARTY OTHER THAN STEVEDORE</i>	6.4	1	2.44
<i>CARGO DAMAGE BY STEVEDORES</i>	7.1	0	0.00
<i>CARGO DAMAGE BY 3RD PARTY OTHER THAN STEVEDORES</i>	7.2	0	0.00
<i>THEFT & PIRACY</i>	8	0	0.00
<i>POLLUTION/SPILL AND DUMPING OF BUNKER/SLUDGE/GARBAGE</i>	9	0	0.00
<i>DETENTION BY PORT STATE</i>	10.1	0	0.00
<i>ARREST/CONFISCATION BY AUTHORITIES</i>	10.2	0	0.00
<i>DAMAGE DURING DRY DOCKING AND/OR SHIP REPAIRS IN REPAIR YARD</i>	11	0	0.00
<i>DAMAGE TO OWN SHIP BY BARGE WHILE DOUBLE BANKING</i>	12	0	0.00
<i>STOWAWAY</i>	13.1	0	0.00
<i>MISSING/RUN-AWAY CREW/OVERBOARD</i>	13.2	0	0.00
<i>CRIME/SMUGGLING/DRUG ABUSE</i>	13.3	0	0.00
<i>DEATH OF PERSONNEL BY DISEASE OR SICKNESS</i>	13.4	0	0.00
<i>DEATH OF PERSONNEL BY ACCIDENT</i>	13.5	0	0.00
<i>DEVIATION OF VESSEL FOR REPATRIATION AND/OR LANDING OF PERSONNEL DUE TO INJURY/SICKNESS/RESCUE OPERATIONS</i>	13.6	0	0.00
<i>SERIOUS INJURY/SICKNESS TO PERSONNEL (NO DEVIATION)</i>	13.7	9	21.95
<i>MINOR INJURY TO PERSONNEL</i>	13.8	7	17.07
TOTAL		41	





■ Series1






25

FLEET CASUALTIES

FLEET CASUALTIES


<i>CATEGORY</i>	<i>CODE</i>	<i>NUMBER OF ACCIDENTS</i>	<i>PERCENTAGE OF TOTAL</i>
<i>CREW ERROR</i>	<i>1</i>	<i>0</i>	<i>#DIV/0!</i>
<i>3RD PARTY ERROR</i>	<i>2</i>	<i>0</i>	<i>#DIV/0!</i>
<i>MECHANICAL FAILURE</i>	<i>3</i>	<i>0</i>	<i>#DIV/0!</i>
<i>ACT OF GOD</i>	<i>4</i>	<i>0</i>	<i>#DIV/0!</i>
<i>TOTAL</i>		<i>0</i>	




■ Series1


DESCRIPTION	ACCIDENT CODE	NUMBER OF OCCURANCES	PERCENTAGE OF TOTAL
<i>COLLISION WITH OTHER VESSEL</i>	1	0	<i>#DIV/0!</i>
<i>CONTACT DAMAGE WITH DOCK</i>	2.1	0	<i>#DIV/0!</i>
<i>CONTACT DAMAGE WITH FLOATING OR SUBMERGED OBJECT/ICEBERG</i>	2.2	0	<i>#DIV/0!</i>
<i>CONTACT DAMAGE WITH BUOY</i>	2.3	0	<i>#DIV/0!</i>
<i>CONTACT DAMAGE WITH FISHING GEAR</i>	2.4	0	<i>#DIV/0!</i>
<i>GROUNDING</i>	3	0	<i>#DIV/0!</i>
<i>FIRE</i>	4	0	<i>#DIV/0!</i>
<i>HEAVY WEATHER DAMAGE</i>	5	0	<i>#DIV/0!</i>
<i>DAMAGE TO HULL/MACHINERY/CARGO GEAR DUE TO WEAR & TEAR/UNKNOWN REASON</i>	6.1	0	<i>#DIV/0!</i>
<i>DAMAGE TO HULL/MACHINERY/CARGO GEAR DUE TO CREW NEGLIGENCE</i>	6.2	0	<i>#DIV/0!</i>
<i>DAMAGE TO HULL/MACHINERY/CARGO GEAR DUE TO STEVEDORE NEGLIGENCE</i>	6.3	0	<i>#DIV/0!</i>
<i>DAMAGE TO HULL/MACHINERY/CARGO GEAR DUE TO NEGLIGENCE OF 3RD PARTY OTHER THAN STEVEDORE</i>	6.4	0	<i>#DIV/0!</i>
<i>CARGO DAMAGE BY STEVEDORES</i>	7.1	0	<i>#DIV/0!</i>
<i>CARGO DAMAGE BY 3RD PARTY OTHER THAN STEVEDORES</i>	7.2	0	<i>#DIV/0!</i>
<i>THEFT & PIRACY</i>	8	0	<i>#DIV/0!</i>
<i>POLLUTION/SPILL AND DUMPING OF BUNKER/SLUDGE/GARBAGE</i>	9	0	<i>#DIV/0!</i>
<i>DETENTION BY PORT STATE</i>	10.1	0	<i>#DIV/0!</i>
<i>ARREST/CONFISCATION BY AUTHORITIES</i>	10.2	0	<i>#DIV/0!</i>
<i>DAMAGE DURING DRY DOCKING AND/OR SHIP REPAIRS IN REPAIR YARD</i>	11	0	<i>#DIV/0!</i>
<i>DAMAGE TO OWN SHIP BY BARGE WHILE DOUBLE BANKING</i>	12	0	<i>#DIV/0!</i>
<i>STOWAWAY</i>	13.1	0	<i>#DIV/0!</i>
<i>MISSING/RUN-AWAY CREW/OVERBOARD</i>	13.2	0	<i>#DIV/0!</i>
<i>CRIME/SMUGGLING/DRUG ABUSE</i>	13.3	0	<i>#DIV/0!</i>
<i>DEATH OF PERSONNEL BY DISEASE OR SICKNESS</i>	13.4	0	<i>#DIV/0!</i>
<i>DEATH OF PERSONNEL BY ACCIDENT</i>	13.5	0	<i>#DIV/0!</i>
<i>DEVIATION OF VESSEL FOR REPATRIATION AND/OR LANDING OF PERSONNEL DUE TO INJURY/SICKNESS/RESCUE OPERATIONS</i>	13.6	0	<i>#DIV/0!</i>
<i>SERIOUS INJURY/SICKNESS TO PERSONNEL (NO DEVIATION)</i>	13.7	0	<i>#DIV/0!</i>
<i>MINOR INJURY TO PERSONNEL</i>	13.8	0	<i>#DIV/0!</i>
TOTAL		0	

COLLISION WITH OTHER VESSEL	0
CONTACT DAMAGE WITH DOCK	0
CONTACT DAMAGE WITH FLOATING OR SUBMERGED OBJECT/ICEBERG	0
CONTACT DAMAGE WITH BUOY	0
CONTACT DAMAGE WITH FISHING GEAR	0
GROUNDING	0
FIRE	0
HEAVY WEATHER DAMAGE	0
DAMAGE TO HULL/MACHINERY/CARGO GEAR DUE TO WEAR & TEAR/UNKNOWN REASON	0
DAMAGE TO HULL/MACHINERY/CARGO GEAR DUE TO CREW NEGLIGENCE	0
DAMAGE TO HULL/MACHINERY/CARGO GEAR DUE TO STEVEDORE NEGLIGENCE	0
DAMAGE TO HULL/MACHINERY/CARGO GEAR DUE TO NEGLIGENCE OF 3RD PARTY OTHER THAN STEVEDORE	0
CARGO DAMAGE BY STEVEDORES	0
CARGO DAMAGE BY 3RD PARTY OTHER THAN STEVEDORES	0
THEFT & PIRACY	0
POLLUTION/SPILL AND DUMPING OF BUNKER/SLUDGE/GARBAGE	0
DETENTION BY PORT STATE	0
ARREST/CONFISCATION BY AUTHORITIES	0
DAMAGE DURING DRY DOCKING AND/OR SHIP REPAIRS IN REPAIR YARD	0
DAMAGE TO OWN SHIP BY BARGE WHILE DOUBLE BANKING	0
STOWAWAY	0
MISSING/RUN-AWAY CREW/OVERBOARD	0



■ Series1





0 1 1 1

NEAR MISS reports for 1390-91(Negligence)

Vessel	SM	COMPANY	Date Occurred	Date Report Received	00/1/1900	Master	Brief Description
GOLAFRUZ	3	SAPID	30.03.2021	22/3/2021	B.ABBAS	JALAL POOR MAHDI	ON 2021/03/22 AT16:20 WHILE MT.ATEELA WAS PASSING ROPES FOR BEING ALONG SIDE. SAFETY OFFICER OBSERVED THAT THE ONE OF ROPES IS PASSED THROUGH STANCHIONS AND RIGGED AROUND WEAK POINT.
DEVREZ	6	SAPID	31.03.2021	26/3/2021	BIK OPL ANCHORAGE	P.EJLALI	On 06.03.2021 at 10:00 vessel was in BIK OPL chief officer during safety round in engine room , it found that one portion of safety guard around the first floor is not properly secured .
BEHDOKHT	2	SAPID	29.03.2021	28/3/2021	LAEM CHABANG AREA	A.BONYADI E. K.	During approaching to Laemchabang anchorage, after giving E.O.P to the eng. room & after filling of pre-arrival checklist & testing of steering gear, duty officer did not keep-on the both steering pumps. Mean while the next duty officer did not take over properly the status of navigational equipment when the wheel was on the hand steering mode, according to the company and master standing order before vessel arr. and dep. Both steering pump must be switched on to make sure it's tested & is in correct function. summary : 1- O.O.W not prepared the vessel correctly for arrival. 2- Not handing over correctly to incoming officer of the watch. 3-Taking over officer not take over the bridge equipment correctly.
DEVREZ	6	SAPID	31.03.2021	28/3/2021	BIK ANCHORAGE	P.EJLALI	On 28.03.2021 at 03:00 while vessel was in BIK anchorage and wind speed up to 40 knot duty officer found other vessel at range 0.8 NM was dragging anchor and call master inform to VTS. VTS inform to other vessel always keep her engine on short notice, position frequently checked and anchor party stand by during this weather condition
BEHDOKHT	2	SAPID	30.03.2021	30/3/2021	SONGKHLA PORT	A.BONYADI E.K	During loading of MDF at songkhla port, after completion of loading cargo hold no.2, ch.off instructed duty officer to close the hatch cover .after switching on the hatch cover's pump & closing one pontoon of hatch cover,unexpectedly the flexible hyd.pipe burstd due to its weakness & old age and it caused alot of oil splashed on cross deck.fortunately, no oil seeped into the sea & the cargo hold.
ARTIN	3	SAPID	31.03.2021	30/3/2021	MINA SAQR PORT BERTH NO.8	M.NOURI	ON 29.03.2021 AT 09:40 LT DURING THE UNBERTHING FROM BERTH NO.8 AT MINA SAQR, MASTER INSTRUCTED 2ND OFFICER TO LET GO THE BOTH AFT SPRING MOORING LINES. WHEN MOORING MAN WAS STILL ENGAGED IN CLEARING THE 2ND AFT SPRING LINE FROM THE BOLLARD ON THE JETTY, 2ND OFFICER INSTRUCTED THE WINCHMAN TO HEAVE UP THE SPRING LINE. FORTUNATELY THE MOORING MAN IMMEDIATELY CLEARED HIS HAND FROM THE MOORING LINE BEFORE HIS HAND BEING CAUGHT BETWEEN MOORING LINE & BOLLARD. FORTUNATELY NOTHING HAPPENED TO HIS HAND

NEAR MISS reports for 1390-91(Negligence)

AMINA	3	SAPID	31.03.2021	31/03/2021	BANDAR ABBAS	A.ARMANDEI	As the bosun instructed by duty officer to attend STS operation and made fast bunker vessel on STBD main deck, bridge team observed bosun and one of deck crew(A.B) are proceeding without proper PPE. Master present on the bridge at the time, stopped their unsafe act and instructed them to use proper PPE.
AMINA	3	SAPID	31.03.2021	31/03/2021	BANDAR ABBAS	A.ARMANDEI	During STS operation with bunker vessel (oriental gulf), while the bunker vessel was approaching and intending to get alongside, lack of attending crew on our own vessel causes improper operation, the bunker vessel could not get properly alongside on the first attempt. Rest of deck crew called immediately and the bunker vessel got alongside safely. As the bosun were instructed in advance to arrange deck crew for safe operation but unfortunately he underestimated operation and attending with insufficient number of deck hands. This situation could cause accident onboard both vessels and led to a real case of emergency. bosun warned regarding his miss handling/management.
AREZOO	1	SAPID	04.03.2021	04.04.2021	B.Abbas	R.TOHIDLOO	While galley staff engaging with washing found that water splashing with high pressure into hotplate system & switch board.
AREZOO	1	SAPID	04.03.2021	25.03.2021	B.Abbas	R.TOHIDLOO	Found that engine staff prepare garbages(paper,box,wood) to over board while vessel at anchorage area. and fortunately by another vigilant staff ceased the job and no any garbages over board.
OURA	2	SAPID	04.10.2021	06.04.2021	bedi anchorage	.F.EBRAHIM	ON 06.04.2021 @ 13:00 WHILE CRANE NO 4 STOPED FOR REPAIR ON ELECTRIC WIRE DRUM . THE GRAB MOVED TO THE DECK AND IN CLOSE POSITION BROUGHT ON MAIN DECK STBD SIDE . HOOK DISCONNECTED AND CRANE MOVED TO THE RIGHT SIDE TO TOP OF HOLD NO 5 IN HORIZONTAL POSITION AS PER DUTIES ON JOB . WHILE CRANE WAS AWAY FROM GRAB AND HOOK ONLY DISCONNECTED, THE GRAB OPENED ACCIDENTALLY IN MAIN DECK AND UNBALLANCED TO OVER BOARD . THE GRAB BROKEN THE SHIPS RAILING AND DAMAGED TO GANGWAY PLAT FORM AND FALL IN TO THE WATER IN POSITION 22 38.996 N 070 04.516 E WITH DEPTH OF 16 METERS AT BEDI ANCHORAGE . SAME TIME AWEIGHT WIYH TWO LIFE RING AND ROPE ABOUT 25 METERS CONNECTED AND DROPED AT POSITION FOR MARKING THE POSITION OF THE GRAB . OFFICERS PRESENT AT THE TIME ACCIDENT CH/OFF /2ND OFF ON DECK CH ELEC ON CRANE PARK POSITION ASS ELECT IN THE CRANE BOSUN ON DECK CARPENTER ON PARKING POSITION AB INSIDE CRANE OS ON DECK
AMINA	3	SAPID	12.04.2021	13/4/2021	BANDAR ABBAS	A.ARMANDEI	On 11th April-2021 at 1450 HRS(SMT), once cleaning and maintenance done on the fresh water hydrophore tank, second engineer attend to pressurize hydrophore up to designed pressure, suddenly side reading glass broken and fresh water splashed over electrical box that was located nearby. fortunately the box was covered already and no damage/incident taken place. This could cause serious danger of electric shock and/or damage to electrical equipments.
DELBIN	6	SAPID	22.04.2021	20.04.2021	Tasucu(Turkey) Anchorage	H . GOLESTANI	During carry out maintenance on fwd mast when a crew which working on top declined, his safety helmet fall down from his head on the deck surface. Fortunately his safety helmet hit the ground in opposite side of the safety representative supervising him.

NEAR MISS reports for 1390-91(Negligence)

DELBIN	6	SAPID	22.04.2021	16.04.2021	Tasucu(Turkey) Anchorage	H . GOLESTANI	During CH/OFF routine inspection with BOSUN , found one A/B working afloat without safety harness .
JAIRAN	1	SAPID	24.04.2021	24.04.2021	BIKPORT (JETTY NO.34)	M.NABIZADEH SH.	On 23.04.2021 at around 22:00 hrs while vessel was alongside in BIK jetty no.34, After several tele conversation with manning company new oiler Mr MOJTABA SEKHAVATPOUR PC NO. OK9228 and new 2nd Eng Mr MOHAMMAD GHASEMPOURFARSANI PCNO. 172990 joined the vessel without having a "negative corona test result" ready at hand and they stated that the result will be ready by the following date. Therefore, As advised by H.O., master instructed them and emphasized clearly that before the result is obtained, they shall remain quarantined in their cabin (shall even have their meals in their cabins) and under no circumstances can go to work or any public space before their test result is reported. On the following date (24.04.2021) at 11:00 hrs, despite clear instructions of Master and without his consent and information, 2nd engineer imprudently and due to an absolute negligence ordered the new oiler to proceed to Engine store and receive working suits. Subsequently ordered him to start working in E/R Change room! Unfortunately Master was called by telephone from HO at 13:30 hrs with the news of "Positive test result" for mentioned crew. Immediately Safety officer was informed, called and looked for Oiler in his cabin but he was not there. So he called E/R and surprisingly found that the mentioned crew had been sent to work contrary to Master's instruction. He was immediately sent to his cabin to collect all his belongings and luggage to prepare for signing off; all ship's personnel instructed to keep social distancing with mentioned crew and to wear protective masks; all saloon seamen were ordered to disinfect all spaces and alleyways. 2nd Engineer was warned verbally by master that clear instructions shall be strictly followed and such mistakes from senior officers in management level is not accepted and could lead to fatal, uncontrollable and very dangerous situations onboard ships. Mentioned crew was finally signed off on 24.04.2021 at 14:00 Hrs.
DELICE	6	SAPID	24.04.2021	24.04.2021	KHOWR-E-MUSA ANCHORAGE	ALIREZA MOAREFIAN	A few pieces of pipes were found in front of fan room fire flap (2nd deck beside the funnel), causing an obstruction for closing the flap.
ARTMAN	2	SAPID	24.04.2021	21/04/2021	MALACCA STRAIT		ON DATE 20/04/2021 DURING SECURITY GUARD EMBARKATION WHILE CRANE MAN WANTED TO BRING SECURITY GUARD EQUIPMENTS ON BOARD FROM ALONGSIDE BOAT AT THIS MOMENT WHEN THE SG EQUIPMENTS CLEARD FROM THE BOAT ,SG PERSONS STANDING BELOW THE EQUIPMENTS AND THEY DONT CARE ABOUT CREWS WARNINGS.
DELICE	6	SAPID	25.04.2021	26.04.2021	KHOWR-E-MUSA ANCHORAGE	.ALIREZA MOAREFIAN	While transferring auxillary engine cylinder head using over head crane ,one of the crew was found to be standing underneath .
CLAVEL	6	SAPID	04.28.2021	10/4/2021	B.ABBAS SHAHID RAJAE PORT.	MOHSEN GOHARDEHI	At 04:12 / 10.04.2021 During disembarking pilot from pilot ladder, duty officer observed that pilot intending to disembark without proper PPE specially lifejacket.
CLAVEL	6	SAPID	04.28.2021	26.04.2021	KHOWR-E-MUSA ANCHORAGE	MOHSEN GOHARDEHI	☐ During ANCHOR watch, duty officer observed that one of crew not wearing safety helmet properly (without chin strap) while entering C.O.T 7 starboard side for pump inspection on main deck.

NEAR MISS reports for 1390-91(Negligence)

BAVAND	2	SAPID	04.05.2021	01.05.2021	E.CHINA SEA	F.RABIE	After 3 days ventilation of cargo hold washing tank & checking amount of oxygen, during cleaning of mentioned tank one of entered crew feel dizzy and in-active. They quickly informed bosun and with help of ch.off took him out. He feel better after drinking some water and getting rest.
JAIRAN	1	SAPID	12.05.2021	12.05.2021	BAY OF BENGAL	NABIZADEH SH.	ON 10.05.2021 WHILE INSPECTION OF MASTER FROM GALLEY HE FIND THAT COOK AND GALLEY BOUY WORKING IN GALLEY WITH SLIPPERS.
AMINA	3	SAPID	13.05.2021	13/5/2021	SHUAYBAH ANCHORAGE	A.ARMANDEI	<p>As the generator No.2 required to sump oil change over according to its running hours, engine staff attended to renew oil and inspect generator sump, during operation and inspection of the generator sump, huge volume of rags found inside the sump. Fortunately oily rags did not cause blanking of filters.</p> <p>This generator was running on load during maneuvering and departure of port of MINA SAQR and as well as approaches to SHUAYBAH port.</p> <p>Presence of huge amount of rags inside the oil and sump could cause blanking oil filter and activating safety shut down of the on load generator and ultimately could lead to over load others parallel AUX engines and their failure and/or others machinery failure during course of maneuvering of the fully loaded vessel with draft restriction.</p> <p>This incident could lid the vessel to the main machinery failure and real case of emergency as well as serious damage to the generator.</p> <p>Also need to mention that the rags was containing acrylic particles which could accelerate wear/tear and damage of main parts of generator.</p> <p>Investigation done for the reason of this incident, found out during major overhauling in dry dock, all cleaning materials(rags) are left inside of the oil sump, and the final inspection not carried out by former onboard engine staff.</p>
MIAMIPRIDE	2	SAPID	14.05.2021	14.05.2021	VIZAG PORT (INDIA)	E.BRAHIM KHOJASTEH NEJAD	<p>VSL WAS UNDER PILOTAGE WITH TWO OLD EXPERT PILOTS IN NARROW CHANNEL BASIN WITH OCCUPIED LEFT&RIGHT SIDE MOSTLY LARGE VSLs.VSL HDG WAS 330 AND SPD 4--4.4KTS,ENG ON D/S AHD WHEN THE VSL ENTERED 2ND INNER TURNING BASIN CLOSED TO BASIN Nr REWW Q-1 &Nr EQ-1 A(under Construction).PILOT ORDERED STOP ENG AND MID SHIP WHEEL'AFter 2MINUTES SAID D/S AST(FWD &AFT TUG ALREADY MADE FAST FROM CNTR LEADS). BUT UNFORTUNATELY ENGINE NOT RESPOND AND CAPTAIN CALLED ENGINE ROOM TO RECTIFY THE PROBLEM AND DUTY ENGINEER SAID THAT AIR PRESSURE GETS DOWN AND ENGINE WILL NOT RESPOND .PILOT AGEIN ORDERED D/S AST BUT NOT RESPONDING CAPTAIN ORDERED TO PUT THE ENGINE ON SLOW ASTERN AND THEN HALF ASTERN BUT ENGINE NOT RESPONDED ANY MORE. SINCE TWO TUGS TRIED TO STOP THE VESSEL WHILE THE VESSEL WAS APPROCHING INTO THE TURNING BASIN WITH 4 KNOTS SPEED. AFTER THAT 2ND PILOT IMMEDIATELY ASKED PORT CONTROL TO ARRANGE THE ADDITIONAL TUG TO STOP THE VESSEL AND PREVENT COLLISION ON URGENT . SO THAT THE ADDITIONAL TUG CAME ON STBD MID SHIP AND PUSHED THE VESSEL PREVENTED AHD MOVEMENTS TOWARDS Nr. EQ-1 A. VSL COMPLETED TURN IN THE BASIN AND. CONSEQUENTLY THREE TUGS PUSHED THE VESSEL SMOOTHLY TO BETHING POSITION NO.EQ-4</p>
CLAVEL	6	SAPID	15.05.2021	13.05.2021	BUSHEHR PORT	.MOHSEN GOHARDEHI	<p>While vessel was casting off bushehr berth on single up to one spring (FWD & AFT), on master order and pilot advise all line cleared from jetty bollards, unfortunately spite of AFT station mooring team skillful & fast action to retrieve last line, AFT spring entangled in sea bed just beneath of bollard, Then immediately as per risk assessment which has been made earlier, requested port control via pilot and asked for tug assistance. Tugs & mooring gang attended in a very short time to keep the vsl alongside and finally & hopefully by the use of port tug, vessel mooring wire cleared without damage to wire and/or personnel. .</p>

NEAR MISS reports for 1390-91(Negligence)

BASKAR	2	SAPID	15.05.2021	2021.05.14	B.ABBAS INNER ANCHORAGE		AT B.ABBAS INNER ANCHORAGE WHILE CHIEF MATE TAKING SAFETY ROUND ON DECK, OBSERVED THAT WORKSHOP ENGAGED IN WELDING OF SHIPS HANDRAILS IS NOT USING PROPER PERSONNEL PROTECTIVE EQUIPMENTS AND HIS WELDING GOGGLES REMAINS UNUSED BEHIND HIM DURING WORK PROGRESS.
GANJ	3	SAPID	17.05.2021	17.05.2021	FANGCHENG ANCHORAGE	A.BONCHEH	On 17/05/2021, during the safety round on deck, noticed that one chipping machine electrical cable is damage, the job was immediately stopped and defective machine transformed to electrical work shop for repair.
MIAMIPRIDE	2	SAPID	21.05.2021	14.05.2021	VIZAG PORT (INDIA)	EBRAHIM KHOJASTEH NEJAD	VSL WAS UNDER PILOTAGE WITH TWO OLD EXPERT PILOTS IN NARROW CHANNEL BASIN WITH OCCUPIED LEFT&RIGHT SIDE MOSTLY LARGE VLS.VSL HDG WAS 330 AND SPD 4-4.4KTS,ENG ON D/S AHD WHEN THE VSL ENTERED 2ND INNER TURNING BASIN CLOSED TO BASIN Nr REWW Q-1 &Nr EQ-1 A(under Construction).PILOT ORDERED STOP ENG AND MID SHIP WHEEL'AFter 2MINUTES SAID D/S AST(FWD &AFT TUG ALREADY MADE FAST FROM CNTR LEADS). BUT UNFORTUNATELY ENGINE NOT RESPOND AND CAPTAIN CALLED ENGINE ROOM TO RECTIFY THE PROBLEM AND DUTY ENGINEER SAID THAT AIR PRESSURE GETS DOWN AND ENGINE WILL NOT RESPOND .PILOT AGEIN ORDERED D/S AST BUT NOT RESPONDING CAPTAIN ORDERED TO PUT THE ENGINE ON SLOW ASTERN AND THEN HALF ASTERN BUT ENGINE NOT RESPONDED ANY MORE. SINCE TWO TUGS TRIED TO STOP THE VESSEL WHILE THE VESSEL WAS APPROCHING INTO THE TURNING BASIN WITH 4 KNOTS SPEED. AFTER THAT 2ND PILOT IMMEDIATELY ASKED PORT CONTROL TO ARRANGE THE ADDITIONAL TUG TO STOP THE VESSEL AND PREVENT COLLISION ON URGENT . SO THAT THE ADDITIONAL TUG CAME ON STBD MID SHIP AND PUSHED THE VESSEL PREVENTED AHD MOVEMENTS TOWARDS Nr. EQ-1 A. VSL COMPLETED TURN IN THE BASIN AND. CONSEQUENTLY THREE TUGS PUSHED THE VESSEL SMOOTHLY TO BETHING POSITION NO.EQ-4
DARYABAR	3	SAPID	22.05.2021	19.05.2021	ASSALUYEH ANCHORAGE	M.ESFANDIARI	On 19.05.2021 at 17:00 hrs LMT during safety round of ch/off on the deck it was found that some paint drums are kept on the deck. The matter informed to bosun and he notified deck crew members in turn that due to fire hazardous nature of paint and similar products they need to be stored in paint store only, whether in large or small quantity.
AYSAN	1	SAPID	26.05.2021	17.05.2021	shuaibah anchorage	ALIREZA KARIMI	On 2021.05.17 at 0830 at shuaibah anchorage while v/l was awaiting for berthing instruction, one of crew member (A.B) attended ships crane No. 2B for checking crane condition suddenly observed wire of crane twisted irregularly around the drum which fortunately before using crane informed to CH.OFF and ELEC.OFF1 After investigation found out that slack wire limit switch is out of order causing the wire twisted around the drum irregularly.
BAHJAT	2	SAPID	27.05.2021	24.05.2021	vessel at magdalla anchorage area-lat 20		ON 22.05.2021 while vessel was at MAGDALLA anchorage area and vessel engaged to cargo discharge operation, suddenly duty officer observed that crane operator cannot control crane (grapes), due to heavy swell .so that chief officer immediately informed by duty officer and cargo operation stopped for safety of ship and stevedores onboard
AMINA	3	SAPID	27.05.2021	05/14/2021	SHUAIBAH BERTH No.7		

NEAR MISS reports for 1390-91(Negligence)

ATEELA 1	6	SAPID		29.05.2021	E ,BND anchorage	H.HESSAM	On 28.05.2021 @ 2148 hrs(LT) while our good vessel was at anchor in position , Lat: 27 05.11 N . 056 12. 55 E and at the time sea condition was rough. wind speed: 20 kts, wind direction: SW'ly. MV J.Pioneer (container vessel), Call sign: HOQQ, MMSI No: 355473000, IMO NO.:009116711 proceeding toward Rajaei port and intending to pass ahead of my vessel with CPA zero . we informed port control and wake up signal has given.Then control called her and request her master alter course to port side and pass our vessel safely, still she did not alter her course as much as to avoiding close quarter situation, captain immediately give order to call anchor party and he announce to Port Control that she did -not alter course enough to avoid risk of collision & most probably she may have a collision wt us. Fortunately when her Accommodation passed ahead of my vessel her CPA was around 10 mtrs, The danger was imminent and after she passed , control was in doubt and ask us weather she safely cleared or not?
ATEELA 1	6	SAPID	29.05.2021	2021.05.28	27 05.11 N /056 12.55 E ,BND anchorage	H.HESSAM	On 28.05.2021 @ 2148 hrs(LT) while our good vessel was at anchor in position , Lat: 27 05.11 N , 056 12.55 E and at the time sea condition was rough , wind speed: 20 kts, wind direction: SW'ly. MV J.Pioneer (container vessel), Call sign: HOQQ , MMSI No: 355473000 , IMO NO.:009116711 proceeding toward Rajaei port and intending to pass ahead of my vessel with CPA zero , we informed port control and wake up signal has given.Then control called her and request her master alter course to port side and pass our vessel safely, still she did not alter her course as much as to avoiding close quarter situation, captain immediately give order to call anchor party and he announce to Port Control that she did not alter course enough to avoid risk of collision & most probably she may have a collision wt us. Fortunately when her Accommodation passed ahead of my vessel her CPA was around 10 mtrs, The danger was imminent and after she passed , control was in doubt and ask us weather she safely cleared or not ?
AREZOO	1	SAPID	29.05.2021	17.05.2021	AT PORT	R.TOHIDLOO	DURING BERTHING OPERATIONTO AFTER PASSING ALL LINES TO THE JETTY, WHILE TIGHTENING THE ROPES FOR FINALASATION OF BERTHING DUE TO MISS OPERATION OF WINCH BY SHIP STAFF. CAUSE HAZARDOUS SITUATION AND MAY CUASE PARTING THE ROPES AND INJURY TO PERSONS.
BAHJAT	2	SAPID	05.30.2021		Gulf of Khambahat(.CH.BARZEGARI.KH	ON 23.05.2021 while vessel was at MAGDALLA anchorage area and vessel engaged to cargo discharge operation, suddenly duty officer observed that crane operator cannot control crane (grapes), due to heavy swell (change of tide) .so that chief officer immediately informed by duty officer and cargo operation stopped for safety of ship and stevedores onboard
TERMEH	3	SAPID	05.30.2021	2021.05.30		RAJ TOOSI	ON 2021.05.30 , At 08:30 SMT While Vessel Was In B.abban Anchorage 2nd.officer Observed In Forward Station For Anchore Party,One Of Deck Crew ,,os,, Was Without Protective Safety Gear
DEVREZ	6	SAPID	05.31.02021	22.05.2021	ASSALUYEH ANCHORAGE	P.EJLALI	On 22.05.2021 at 14:20 when vessel was in IR ASA anchorage for checking and testing of steering ch-off was in steering room found near of electrical panel don't have any mate for insulation electrical to deck .

NEAR MISS reports for 1390-91(Negligence)

A.ARMANDEI +G40:G42	3	SAPID	06.01.2021	05/26/2021	SHARJAH OPL	A.ARMANDEI+AG40:G4 2	<p>On 26th-May 2021 at 1510 HRS LT while vessel was prepared for departure and, heaving up anchor was in progress by anchor party. Engine test carried out by bridge team on ASTERN and AHEAD movement. Few minutes later anchor found aweigh and master ordered engine to run D.S.AHEAD, Officer of the watch complied with master order and moved the engine telegraph from STOP to D.S.AHD. Main engine started but unable to pick up RPM, and after few seconds RPM reduced and finally engine stopped. D.S.AHD order repeated once more without any response.</p> <p>Master instructed anchor party to be ready for emergency anchoring. Contact made instantly with engine room to find out result and issues.</p> <p>Vessel's head start to turn as the anchor was aweigh and engine was not available. Heavy dense traffic of anchored vessels in vicinity, and un-availability of engine movement caused dangerous situation and could lead the vessel to close quarter situation and an emergency anchoring operation.</p> <p>Finally engine made ready D.S.AHD order responded by main engine</p>
DEVREZ	6	SAPID	06.04.2021	22.05.2021	ASSALUYEH ANCHORAGE	P.EJLALI	<p>On 22.05.2021 at 14:20 when vessel was in IR ASA anchorage for checking and testing of steering ch-off was in steering room found near of electrical panel don't have any mate for insulation electrical to deck .</p>
GOLSAR	3	SAPID	06.05.2021	27.05.2021	At Sea	A.Nemati	<p>On 27.05.2021 At 0300 hrs/lt, While approaching to SHUAIBA anchorage, anchor party proceed to fwd station by master order. At that time when anchor party presented at fwd station, officer in charge found out an OS by common clothes at the anchor station. At the Time, Officer in-charge warned him & sent him back to change & use PPE.</p>
AMINA	3	SAPID	06.06.2021	06/06/2021	SHUAIBA PORT, BERTH No.11	A.ARMANDEI	<p>On 2021/06/06 at 1130 Hrs Lt, during discharge operation from cargo hold No.2 duty officer observed signal man has standing on the hatch coming rail where there is no any safety guards. Safety guards/rails was already prepared and located on PORT and STBD hatch cover.</p> <p>Operation ceased instantly by duty officer and signal man warned about his unsafe act and asked to stay on hatch cover where the safety guards available. Forman informed in this regard and chief officer instructed to halt operation if any unsafe/dangerous situation observed. All safety pre-cautions was already taken ship's staff, there is no any excuse to bypass any safety matters.</p>

NEAR MISS reports for 1390-91(Negligence)

ARSHAM	2	SAPID	06.09.2021	06.09.2021	MAGDALLA OPL ANCHORAGE	H. DELBARY	<p>Kindly note Kham bat VTS inform v/l on 16.05.2021 around 14:30hrs LT for prepare to heave up anchor at 17:00hrs LT for leaving the port area and proceed to open sea due to storm warning.</p> <p>Fuel oil purifier no.1 was in overhauling progress (as job list plan for discharging port), around 13:00hrs bridge informed engine department to make the engine ready for sailing because of heavy weather, therefore all precautions measured and applied to make everything ready asap.</p> <p>H.O. purifier overhauling completed at 17:00hrs LT. and started and checked, waiting 1 HR to ensure proper operation, H.O. purifier found in good working order, meanwhile engine gear test carried out at 17:00hrs LT, found satisfactory. Informed bridge at 19:30hrs LT that the engine is ready for sailing, but master decided to stay at anchorage because of safety reason because of he was not sure about full readiness of her engine for heavy weather and to prevent encounter to TRS (TAUKTAE) & with considering the time was too late to heave up anchor and proceed to open sea & crossing TRS.</p> <p>At date 2021.05.17on 08:10hrs LT Kham hat VTS again advised to heave up anchor for leaving the area , engine gear tested on 08:42hrs LT, and Heaved up Anchor and VSL was under way at 09:00hrs LT with considering not possible to cross TRS and shall proceed southerly for drifting , VSL exit from port limit at 09:10hrs LT , B.O.P @ 13:30hrs LT. Continue sailing with max M/E rpm 92 to prevent overloading because of heavy rough sea / strong current & swells and keep close monitoring and maintaining all parameters at safe margin. At date 2021.05.17on 13:50hrs LT in position Lat: 20 31.9 N Long: 072 27.8E , M/E unit no.5 upper cooling jacket Ruptured and caused M/E J.C.W low pressure and slow down the M/E & Tried out to isolate J.C.W to the unit NO.5 and cut out unit no.5 and resume propulsion with 5 units and proceeds the ship to the safe location for dropping anchor and rectify the engine problem.</p> <p>Kham bat vts informed accordingly & Advised for drop anchor in position 6 nautical mile away from v/l (20 27.7N 072 32.9E outside the vts limit reporting line) , but v/l could not cope with strength current pushing the v/l northerly due to low RPM (maximum sp:1 knot some time minus and informed VTS that v/l is not under command on channel 09 and finally v/l forced to dropped anchor in posn 20 31.55N 072 28.36 E @ 15:30hrs LT , due to engine problem & Kham bat vts informed accordingly .</p> <p>Then, tried out to prepare and commence for replacing unit no.5 upper jacket with new spare, but take advice from SM2 to hold on M/E power at this situation.</p> <p>Finally at 19:50 hrs. LT on 17.05.2021 engine gear test carried out found satisfactory to heave up both anchors for safety of v/l away from closely shallow patch due to dragging of the v/l toward same shallow patch. At 17.05.2021 on 21:36hrs LT, VSL was under way in position 20 35.9 N 072 27.46E in order to proceed to safe position and away from nearest shallow patch areas with maximum RPM 72(due to one unit cut out) &</p>
ARTMAN	2	SAPID	06.11.2021	05/06/2021	YANGJIANG PORT	S.D.H.NODEHI	<p>ON DATE 04/06/2021 AFTER COMPLETION OF DISCHARGING,DURING CLEANING OF CARGO HOLD,CHIEF OFFICER OBSERVED ONE OF CREW NOT USING OF P.P.E AND IMMEDIATLY STOPEO THE OPERATION.</p>
BAHJAT	2	SAPID	06.12.2021	29.05.2021	Gulf of Khambahat	CH.BARZEGA+B46:G47 RI.KH	<p>On 2021/05/29 at 10:30 while vessel was at MAGDALLA anchorage area for discharge of cargo (gypsum in bulk),Buson and other deck crew were engaged to park the grab of crane no. 4 in her place , due to heavy s well in anchorage area and v/l rolling , suddenly grab moved ,cause of gently rolling ,so Buson left hand finger Pressed. Between the body of grab and hatch coming. Unfortunately the first knuckle of his finger scratched.</p>
ARIES	3	SAPID	06.13.2021	10.06.2021	MOZAMBIQUE CHANNEL	D.BANADAKI	<p>AT 0010 LT BRIDGE INFORMED BY DUTY ENGINNER THAT THE AFT WINCH HAD BEEN RUNNING RUNNING DURING DARKNESS WHILE NO BODY WAS WORKING ON AFT WINCH , SO THAT FROM 1700 HRS THE WINCH MOTOR WAS RUNNING UP TO MIDNIGHT .</p> <p>AFTER INVESIGATION , IT CAME TO THE CONCLUSION THAT , DECK CREW WHO WERE DOING MAINTENANCE ON AFT WINCH , HAD FORGOTTEN TO SWITCH OFF THE POWER AFTER COMPLETION OF THEIR TASKS & HAD NOT INFORMED NITHER TO THE BRIDGE NOR THE ENGINE ROOM.</p>

Recommendation by Vessel	Validity	Category
SAFETY IS ALWAYS PRIOR OVER CONVENIENCE, BEFORE COMMENCEMENT OF SUCH OPERATION THE CREW SHALL BE BERIFIED ABOUT THEIR DUTIES FOR SAFE IMPLEMENTATION.	Y	
It requested from second engineer to make aware the engine's crew from the consequence of such negligence.	Y	
all O.O.W should be prepared pre-arrival and pre-departure check list & make sure the condition of navigatioal status is correctly followed as per company ISM procedure and master standing order	Y	
At anchoring time check vessel position and keep sharp lock out for other vessel may be dragging anchor	Y	
close inspection of hatch cover's hyd. pipe before arriving to the port & regular maintenace of hatch cover 's flexible hyd.pipes	Y	
ALL OFFICERS & CREW WELL BRIEFED REGARDING SAFE MOORING OPERATION. RESPONSIBLE OFFICER / PERSON TO BE VERY VIGILANT DURING THE MOORING OPERATION. PROPER COMMUNICATION TO BE ESTABLISHED BETWEEN RESPONSIBLE OFFICER & WINCHMAN ON BOARD. PROPER COMMUNICATION TO BE ESTABLISHED BETWEEN RESPONSIBLE OFFICER ON BOARD & MOORING MAN ON THE JETTY. CONDITION OF MOORING LINES TO BE VERIFIED WELL BEFORE COMMENCING THE MOORING / UNMOORING OPERATION TO RECTIFY ANY TWISTING OF MOORING LINES OR CLEAR ANY OBSTRUCTION IN MOORING AREA.	Y	

NEAR MISS reports for 1390-91(Negligence)

<p>Further training and familiarization to be carried out about the importance of using PPE. Breifing session will be conducted for all deck crew with respect to proper using of safety gears. Any operation forbidden to carry out on deck with out using suitable PPE.</p>	<p>Y</p>	
<p>Risk assessment to be conducted prior operation, onboard training and familiarization with STS operation/procedure to be carried out. proper number of attending crew to be assigned for such an operation well in advance.</p>	<p>Y</p>	
<p>asked galley staff to be more attention and aware of working place.</p>	<p>Y</p>	
<p>method of garbage segration and collection re explain to him. to be explain at every drill regarding garbage segration ,collection and transferring to shore facility and garbage disposal chart and special area as well paricularly for new employer .</p>	<p>Y</p>	
<p>CHANGE DAMAGED DRUM AND GRAB CONNECT ANOTHER GRAB TO CONTINUE DISCHARGE OPERATION.</p>	<p>Y</p>	
<p>Although the mentioned incident happen due to sudden failure of the machinery equipment, but detail inspection and risk assessment should be done prior any maintenance to minimize such a incident</p>	<p>Y</p>	
<p>Safety helmets should be used with fasten strap to prevent falling when crew members decline or in bad weather and should be a part of their cover not for show off.</p>	<p>Y</p>	

NEAR MISS reports for 1390-91(Negligence)

<p>Concern officer should complete risk assessment form Before commence any jobs on board and then proceed to work. All precautions should be took while carry out jobs on ship's side areas including permit to work, safety protective clothing, safety belt or safety Harness as required, communication tools with duty officer, as well some one should attend them all the time during job completed. When safety harness has to being used that should be secured with a strong point like deck eyes and use appropriate length of such rope, no unnecessary long rope to make fast.</p>	<p>Y</p>	
<p>Manning company shall not send crew without having "negative corona test result" onboard ships.</p>	<p>Y</p>	
<p>During a training session , the crew were once more briefed that even for a short while any garbage , drum , pipes , etc, must not be kept in any place other than designated places. More over , appropriate warning signs were posted.</p>	<p>Y</p>	
<p>AFTER SUCH THIS INCIDENT SECURITY GUARDS INVITED AT THE SHIP DECK OFFICE AND SAFTIES REVIWED</p>	<p>Y</p>	
<p>A training session was held and once more the importance of safety precautions and procedures were outlined. Also crew member were briefed to perform any job/maintenance safely and as per SMS manuals.</p>	<p>Y</p>	
<p>It's brought to the attention of all officers and crew that wearing of safety gears are for their own safety and whatever difficulties arises during using of them but it will guarantee their own safety of life. Safety drill and safety training class must be carried out regularly.</p>	<p>Y</p>	
<p>It's brought to the attention of all officers and crew that wearing of safety gears are for their own safety and whatever difficulties arises during using of them but it will guarantee their own safety of life. Safety drill and safety training class must be carried out regularly.</p>	<p>Y</p>	

NEAR MISS reports for 1390-91(Negligence)

<p>To minimize reoccurrence of such problem, the crews who seems they are weak and cannot sustain such job, they should be given another maintenance job if possible.</p>	<p>Y</p>	
<p>PROPER PPE SHOULD BE WEARED IN ANY WORKING PLACES.</p>	<p>Y</p>	
<p>Thorough examination and precise inspection must be done by ship staff once any major repair/overhauling carried out on machinery equipment, specially during dry dock repairs or any other maintenance carrying out by workshops.</p> <p>Once the job completed its highly important to insure the equipment is ready to use in all aspect. Risk assessment must be provided in this regard.</p>	<p>Y</p>	
<p>TAKE MORE PRECAUTIONS BY ENGINE STAFF WHILE BERTHING OR UNBERTHING OPERATION SIGNIFICANTLY WHEN THE BERTHING OPERATION TAKES LONG TIME TO FINISH.(DISTANCE FROM PILOT STATION AND JETTY WAS 5 NAUTICAL MILES AND PASSAGE WAS IN THE NARROW CHANNEL WITH HIGH TRAFIC &BUSY PORT & TWO INTERNAL TURNING BASIN).</p>	<p>Y</p>	
<p>Further investigation from pilot(Mr.Mousavi)revealed that there was past experience for fleet company and cutted dolphin not removed from sea bed since long time ago, Strongly advised to clear sea bed from any obstruction to avoid such a incident.</p>	<p>Y</p>	

NEAR MISS reports for 1390-91(Negligence)

When welding in progress safety goggles should be worn.(as per SPM Manual, Correct use of goggles provides security against harm to eyes to complete task.	Y	
The assigned crew must inspect the equipment prior to use and electrical officer shall inspect machine on routine basis.	Y	
TAKE MORE PRECAUTIONS BY ENGINE STAFF WHILE BERTHING OR UNBERTHING OPERATION SIGNIFICANTLY WHEN THE BERTHING OPERATION TAKES LONG TIME TO FINISH.(DISTANCE FROM PILOT STATION AND JETTY WAS 5 NAUTICAL MILES AND PASSAGE WAS IN THE NARROW CHANNEL WITH HIGH TRAFIC &BUSY PORT & TWO INTERNAL TURNING BASIN	Y	
Training session for crew members was held right away.	Y	
All crane's must be regularly checked specially before use to make sure working properly.	Y	
Chief officer discussed with duties officer in this matter and wind and sea state must be continuously monitored by duty officer on the watch , so before any bad weather informed to stevedore and in advanced stopped cargo operation	Y	
	Y	

NEAR MISS reports for 1390-91(Negligence)

<p>Write a letter of protest to inform port authority and B.Abbas PSC department to take proper and effectiveness action and inspection to avoid such un safe navigation in future. Request from port control by VHF give a procedures to all vsl about passing other vsl at anchor with a safe distance. Make sure all O.O.W be alert at all time.</p>	<p>Y</p>	
<p>Write a letter of protest to inform port authority and B.Abbas PSC department to take proper and effectiveness action and inspection to avoid such unsafe navigation in future. Request from port control by VHF give a procedures to all vsl about passing other vsl at anchor with a safe distance. Make sure all O.O.W be alert at all time.</p>	<p>Y</p>	
<p>RISK ASSESSMENT TO BE REVIEWD BEFOR COMMENCMENT OF ANY MOORING/BERTHING OPERATRION.AND DUE TO EXCESSIVE NOIS PARTICULARLY IN AFT STATION(ENGINE NOIS) .LEARNING TO ALL STAFF THE HAND SIGNALLING IN RIGHT AND PROPER MANNERS TO AVOID THE SAME.</p>	<p>Y</p>	
<p>Chief officer discussed with duties officer in this matter, chief officer instruct duty officer, wind and sea state must be continuously monitored during the watch, and informed discharge Forman in advance to stop the operation</p>	<p>Y</p>	
<p>Safety Meeting Held And Trained Him.</p>	<p>Y</p>	
<p>In any electrical panel must be keep a mate for insulation of electrical .</p>	<p>Y</p>	

NEAR MISS reports for 1390-91(Negligence)

<p>Engine staff must conduct routine test and maintenance of require machinery which use during maneuvering. All service air bottles must be available during maneuvering to avoid low air pressure while main engine starting. Risk assessment must be conducted by Engine department as well as bridge team and being prepared for any kind of emergency.</p>	<p>Y</p>	
<p>In any electrical panel must be keep a mate for insulation of electrical .</p>	<p>Y</p>	
<p>He received proper training from the officer in-charge of the anchor station at the end of maneuvering to use & wear PPE while onboard.</p>	<p>Y</p>	
<p>Stevedores must be informed in advance regarding the safety requirements by ship, adequate training must be conducted for stevedores by port operation to minimize such a dangerous/near miss situations. Risk assessment must be provided to indicate and eliminate all possible risks.</p>	<p>Y</p>	

NEAR MISS reports for 1390-91(Negligence)

<p>All defective items including CSM item's for main engine unit is require to be attended by ICS surveyor. Essential spare parts is require to supply on board , SSR list send by ship in each calling home port to be follow by SM departments. More encourage for Iranian seafarer is require from head office by increase or if not increase, at least same salary paid by USD or favorite rate in market.</p>	<p>Y</p>	
<p>INFORM TO ALL CREW AS PER ISM, WHEN CLEANING CARGO HOLD SHOULD BE USE OF SUITABLE P.P.E AT ALL TIME.</p>	<p>Y</p>	
<p>Ship staff explained by CH/OFF aboat the risk of working with heavy lift machin ,and The requirement of risk assessment and ap cod to be followed restrictly,Use of proper safety gear emphasize</p>	<p>Y</p>	
<p>ALL OF THE CREW WERE WARNED REGARDING THE CONSEQUENCES OF SUCH A NEGLECT , & THEY HAVE BEEN INSTRUCTED TO REPORT TO THE BRDIGE &/OR ENGINE ROOM THAT ANY EQUIPMENT UNDER MAINTENANCE DURING THE WORKING TIME HAS BEEN SECURED & SWITCHED OFF AFTER THE COMPLETION OF THE TASK.</p>	<p>Y</p>	

Total Number of Cases Reported	50
Number of Valid Near-Miss Cases	50
Number of Irrelevant Near-Miss Cases	0
Percentage of Valid Cases Reported	100.0
Percentage of Irrelevant Cases Reported	0.0

Total Number of Cases Reported	0
Number of Valid Near-Miss Cases	0
Number of Irrelevant Near-Miss Cases	0
Percentage of Valid Cases Reported	#DIV/0!
Percentage of Irrelevant Cases Reported	#DIV/0!

--

--

--

--

--

--

--

--

--

--

--

--

--

--

--

--

--

--

--

--

--

--

--

--

--

--

--

--

--

--

--

--

--

--

--

--

--

--

Total Number of Cases Reported	0
Number of Valid Near-Miss Cases	0
Number of Irrelevant Near-Miss Cases	0
Percentage of Valid Cases Reported	#DIV/0!
Percentage of Irrelevant Cases Reported	#DIV/0!