

Ref : DMA/AIFI/97/C 902

Date: 05/06/2018

Dear Captain
Good Day,

Kindly find the “[New Loss Prevention Bulletin Published – regarding Inaccuracies in Draught Surveys](#)” for your kind attention and necessary precaution measures.

You are requested to confirm receipt , discuss the contents in the next consolidated meeting on board and keep a copy in DA-11 file.

Best Regards,

Ali Mohtasham

Accident Investigation / Fleet Inspection Expert

Department of Maritime Affairs

ROD Ship Management Co.

Dept. Tel No. : +98-21-26100357

Dept. Fax No.: +98-21-26100356

Direct Tel No.: +98-21-23843563

Please reply to dma@sealeaders.com

(Note: This e-mail has been sent as BCC <blind carbon copy to : All R.O.D.-SMC Vessels, to eliminate the lengthy list that would result if this e-mail is printed)

Inaccuracies in Draught Surveys

The Club regularly receives claims arising from alleged shortages of cargo as a result of discrepancies between draught survey results.

Draught surveys by their very nature are not an exact science, and the accuracy of the calculated cargo figure may vary typically by between 0.5 and 1.0%. However, there are occasions when considerable differences in the cargo figures derived from the draught surveys are obtained. The purpose of this Loss Prevention Bulletin is to remind deck officers of the principal sources of errors which may affect the survey results, such that they can be taken into account when shortages in the cargo are found.

Draughts

It is imperative that the draught marks are read as accurately as possible. Ideally this should be done from a boat so that the marks can be approached closely and read. However, poorly painted, rusty, or draught marks covered with marine

growth make reading the draught accurately problematic, therefore it must be ensured, so far as possible, that the draught marks are kept in a readable condition. The presence of wind waves on the water surface will necessitate an estimation of the average draught by observation of the peaks and troughs of the waves against the hull. Darkness and shadows also make accurate reading difficult; therefore good lighting will be required at night. The turn of the hull around the stern leading to elongation of draught marks being viewed from an oblique angle, especially when this has to be done from an adjacent wharf at a higher level, can lead to difficulty in accurately determining the draught.


As an example, an error of two centimetres in the mean draught would lead to an error in the displacement of approximately:

- **68t** – Handysize Bulk Carrier (10,000 – 35,000t deadweight)
- **90t** – Handymax Bulk Carrier (35,000 – 59,000t deadweight)
- **112t** – Panamax Bulk Carrier (60,000 – 80,000t deadweight)
- **300t** – Capesize Bulk Carrier (> 80,000t deadweight)

It is therefore advised to ensure that the inspection and maintenance of the draught marks be included in the planned maintenance system on a vessel.

Density

Although there are numerous possible causes of inaccurate dock water density, it must first be confirmed that the hydrometer being used is of the correct type. There are two types of hydrometer in use, the load line survey hydrometer, and the draught survey hydrometer, the latter being used in this case.





A draught survey hydrometer, calibrated in air, measures the apparent density of the water and is used for determining the weight of the cargo onboard. A load line hydrometer, calibrated in a vacuum, is used to determine the relative density of the water and determine the displacement of the vessel at a given load line. A dock water density reading taken with a draught survey hydrometer showing 1.015 t/m^3 , would show 1.017 t/m^3 when taken with a load line hydrometer, both are correct, the difference between the two of 0.002 is known as the “air buoyancy correction”, however as we want to determine the weight of the cargo on the vessel the density read from the draught survey hydrometer will be used. The draught survey hydrometer is calibrated at a standard temperature. Any deviation from the standard temperature does not require a temperature correction, as the changes in the volume of the vessel and the hydrometer will generally cancel each other out. It must also be ensured that the hydrometer is calibrated regularly to ensure its accuracy, as they can become chipped, damaged and / or contaminated with a film on their surface during use, altering their mass. Hydrometer manufacturers generally recommend they are calibrated after one year, and then every two or three years thereafter.

When determining the dock water density a sample of the dock water should be taken beneath the surface of the water, clear of overboard discharges and deck runoff. In order to ensure an accurate reading the receptacle used to sample the dock water, and the hydrometer, must be clean. When taking the reading the hydrometer must not touch the side of the receptacle and be gently spun to break the surface meniscus of the water. The density reading is then read from the hydrometer stem at the bottom of the remaining meniscus. A number of readings should be taken from each sample, with the average of the readings determined. A number of separate dock water samples should be taken from around the vessel and measured, with the mean of all the average densities used for the draught survey.

If an error is made when determining the dock water density, using a density lower than the actual density will lead to an apparent cargo shortage, with an apparent cargo surplus when a density higher than the actual density is used.

Ballast

A number of errors can occur when determining the ballast onboard. The tank soundings themselves may be incorrect due to difficulties in obtaining accurate soundings when using a sounding rod and rope, with the inherent possibility of reading incorrect depths from the rope due to a lack of markings and the wetness of the rope. When using a metal sounding tape it may be difficult to determine the actual water level from the metal tape. Further, inaccurate soundings may be obtained when the doubler plate at the bottom of the sounding pipe is corroded and worn, increasing the sounding and hence the apparent weight of water in the tank. Often, particularly on older vessels, sounding rods and brass bobs may remain in the sounding pipe, giving readings less than true, as will be the case if the sounding pipe has become blocked with rust scale or other debris, such as rags left in the tank during maintenance or dry-docking. The presence of sediment in the tank covering sounding rods and tapes can also lead to erroneous readings. The figures for the ballast extracted from the sounding book may be in error due to inaccuracies in interpolation or not allowing for the trim or list of the vessel, further, the figures may be calculated assuming an incorrect ballast water density, and it is recommended that ballast tanks are overflowed for a length of time such that a truly representative ballast water sample can be obtained for density determination.

Unfactored Weights

Often weights are not deducted or allowed for when determining the cargo quantity, the commonly forgotten weights are:

- Bilge water present in the cargo holds, machinery spaces, duct keel, void spaces and the chain lockers.
- Swimming pool water.
- Anchor and anchor cable on the seabed, either when at anchor or alongside and an anchor has been deployed as part of the mooring arrangement.
- Silt and mud can accumulate in the double bottom tanks of vessels regularly ballasting in rivers or estuaries. The extra

Loss Prevention Bulletin



weight can give rise to an apparent increase in the cargo loaded.

As an example:

If we assume a single ballast tank with a 500m³ capacity.

On arrival prior to loading the tank is overflowed and full of seawater.

Therefore the assumed weight of water =
500m³ x 1.025 t/m³ = 512.5t.

However, there is 40m³ of mud in the tank.

Therefore the true picture of the tank's contents is as follows:

Water: 460m³ x 1.025 t/m³ = 471.5t

Mud: 40m³ x 1.9 t/m³ = 76t

Total weight of tank contents = 471.5t + 76t = 547.5t

As 512.5t is assumed to be the weight of ballast in the tank, the remaining 35t will appear in the constant.

On completion of loading it is assumed the tank is empty. However, 76t of mud remains, only 35t of which is in the constant, the remaining 41t will appear to be cargo loaded.

Squat

As most mariners know, squat is the bodily sinkage and trimming of a vessel making way with limited underkeel clearance. However, a vessel alongside a river berth may also be susceptible to squat, leading to inaccurate draught readings.

Squat will occur when there is limited space for the water to flow between the vessel and the river bed. In order for the river water to pass between the flat bottom and the river bed there will be an increase in velocity of the water flowing past the hull, and consequently a decrease in the water pressure. The decrease in pressure leads to the ship bodily sinking and also a change of trim. The magnitude of the bodily sinkage and change of trim is difficult to quantify, however, it will be a function of the underkeel clearance, speed of the water, the cross section of the hull in relation to the cross section of the

Loss Prevention Bulletin

river (blockage factor) and the shape of the hull (full form vessels are affected more). Generally full form vessels will trim by the head, and fine line vessels will trim by the stern. If a vessel is passing at the time that the draughts are being read, this may exacerbate the error due to the increased blockage of the river and consequently the vessel may trim and sink more than normal.

Further Factors

Other areas that can lead to errors in the draught survey calculation include the following:

The hydrostatic data and tank sounding tables may not be accurate due to changes to the ship's structure.

On most vessels the ballast tanks suction are located at the aft end of the tanks, as the normal convention is for a vessel to be trimmed by the stern. However, when trimmed by the head, although a ballast pump may have lost suction indicating that the tank is empty, there may be un-pumpable ballast pooled in the forward part of the tank. In addition, if the sounding pipe is towards the aft end of the tank and the vessel is trimmed by the head, then the sounding may also show the tank to be empty, when that is not the case.

Leaking tank valves – when a tank has been sounded and found to be empty, subsequent ballasting / de-ballasting operations could lead to water leaking into the tank, similarly, when ballast tanks are overflowed during discharge operations to show that they are full, water could leak out of the tank prior to the draught survey taking place.

Whilst on passage, depending on the nature of the cargo, water could migrate from the cargo to the cargo hold bilges and be subsequently pumped overboard. If water is found to be accumulating in the bilges while at sea, accurate records of the quantity of bilge water pumped overboard should be kept to help counter any subsequent cargo shortage claim.

Some vessels are susceptible to unsymmetrical hull deflection, this particularly affects smaller vessels due to their larger engine room in relation to their size which pushes the location of maximum sag forward of amidships, leading to inaccurate draught readings.

On older vessels in particular, problems can be encountered due to set in shell plating between the upper wing and double bottom ballast tanks. This can lead to actual displacements less than shown in the hydrostatic data for a given load draught, therefore there can be less cargo onboard than expected.

The position of the hatchcovers can affect the deflection of the hull, particularly on smaller vessels when the open hatch covers may be stowed at one or both ends of a single hold. For draught surveys on all vessels it is recommended that the hatches remain closed to ensure consistency.

Whilst alongside any bunkering, taking of potable water, and discharge of sludge or oily water should be considered when completing the final draught survey.

Where there is any notable difference in the constant between loading and discharge, then this is an indicator that there is an error somewhere in the draught survey, and this should be thoroughly investigated. Throughout a cargo voyage, the constant should be, as the name suggests, fairly constant.

In the event of a cargo discrepancy arising as a result of a draught survey, deck officers are advised to consider the possibility that one or more of the foregoing factors may have contributed to the difference. In particular any substantial change in the constant should be viewed with suspicion and investigated.

Members requiring further information should contact the [Loss Prevention department](#).