

Ref : DMA/AIFI/97/C 964

Date: 26/11/2018

Dear Captain
Good Day,

The recent PSC/FSC inspection reports on board fleet vessels indicate that there has been a repeated deficiency for navigational lights as followings:

- MV Parshad (21/05/2018) navigation light on x-mass tree is not working
- MV Shabgoun (27/05/2018) lower masthead light is not working
- MV Alvan (13/07/2018) Navigation light on x-mass tree out of order
- MV Kiazand (10/07/2018) NUC light is not working
- MV Shamim (10/01/2018) stern light horizontal arc of visibility is 225 degrees
- MV Behdokht (23/10/2018) stern light is not working
- MV Arsham (23/11/2018) Fwd mast head light showing arc of visibility less than 225 degrees

Based on above, Masters are required to ensure that all navigational lights are working and meet the requirements as stipulated in the COLREG regulations.

In this regard Followings shall be checked/verified and if required lights shall be repaired/replaced and the attached table filled in and send to DMA and relevant SM department by 15.12.2018:

- 1- All navigational lights are working properly.
- 2- All navigational lights arc of visibility is complying with the requirements of COLREG.
- 3- Lanterns are clean and shades are transparent.
- 4- If applicable, appropriate anti-reflect paints for interior structure of light housing is applied.
- 5- There is no wastage of the light housing surrounding structure.
- 6- There is no wastage of lantern structure including the hinges.

You are requested to confirm receipt, discuss the contents in the next consolidated meeting on board & keep a copy in the file DA-11 .

Best Regards,

Ali Mohtasham
Accident Investigation / Fleet Inspection Expert
Department of Maritime Affairs
ROD Ship Management Co.
Dept. Tel No. : +98-21-26100357
Dept. Fax No.: +98-21-26100356
Direct Tel No.: +98-21-23843563
Please reply to dma@sealeaders.com

