From: aifi01@sapidshpg.com [mailto:aifi01@sapidshpg.com]

ظ.ق 28:30 08:33 أفريل ,الثلاثاء :Sent

Cc: dma@sapidshpg.com; sm1@sapidshpg.com; 'SM2' <sm2@sapidshpg.com>; sm3@sapidshpg.com;

sm6.tanker@sapidshpg.com

Subject: DMA / AIFI01 - ALL FLEET VESSELS/ DA-11, Precautions to avoid grounding during cargo loading

and unloading (at anchor or berth) at various ports including home ports

TO ALL FLEET VESSEL

Ref: DMA-SAPID/IAFI01/99/C1097 Date: 2020.04,26

In The Name Of God

Good Day, Dear Sir

Considering the recent grounding incidents one of fleet vessels during loading and unloading operation at one of INDIAN ports, refer to furthure DA11 - DMA/AIFI/97/C 970 (12/12/2018), it is imperative that esteemed masters need to take appropriate measures to prevent the risk of grounding.

In doing so followings shall among those measures to be considered:

- 1. A proper risk assessment shall be carried out to identify related hazards / risks and effective measures to be taken to eliminate and/or minimize said hazards.
- 2. Voyage instruction shall be well studied and understood for any limitation at berth.
- 3. Company's requirements for under keel clearance shall be complied with.
- 4. All events to be duly recorded in deck log book.
- 5. At the first opportunity actual sounding around vessel, especially on jetty side shall be taken and compared with chart data and the received information from concerned parties as per voyage instruction.
- 6. The correct density of water shall be used for draft / trim calculation.
- 7. Avoid unnecessary excessive trim by stern so far as practicable.

- 8. Loading condition, vessel's stability and actual draft shall be continuously checked.
- 9. Last stage of loading is more critical specially while trimming the cargo to reach to the desired trim and drafts.
- 10. If in doubt about the available depth of water, commercial department and concerned parties shall be immediately notified.

You are requested to confirm receipt , discuss the contents in the next consolidated meeting on board and keep a copy in DA-11 file.

BEST REGARDS CAPT.A.Momeni.N. Accident Investigation And Fleet Inspection Department Of Maritime Affairs Sapid Shipping Co.

Tel:+98-21-2610 0357 Fax:+98-21-2610 0356 Direct Tel:+98-21-2384 3543

PL'S REPLY TO; <u>dma@sapidshpg.com</u> cso@sapidshpg.com

