Ref : DMA/AIFI/96/C 875 Date: 20/02/2018

Dear Captain Good Day,

We would like to bring to your kind attention that the Port of Fujairah has issued a new Notice to the Mariners requesting the vessels to refrain from anchoring at the restricted anchorage areas adjacent to U.A.E East Coast Territorial waters. If any vessel is found anchored in the restricted area will invite a permanent entry ban, or a fine of AED 10,000/- or both without further clarification by the Port of Fujairah.

Please find herewith attached the NTM 240/2018 issued by the Port of Fujairah, extract of Notice to Mariner No. 148 Version 3 (the restriction is given in paragraph 22 of this notice)& Notice to Mariner No. 10112012 issued by Khorfakkan Port for your kind reference and strict observance.

You are requested to confirm receipt, discuss the contents in the next consolidated meeting on board & keep a copy in the file DA-11.

Best Regards,

Ali Mohtasham Accident Investigation / Fleet Inspection Expert Department of Maritime Affairs ROD Ship Management Co. Dept. Tel No. : +98-21-26100357 Dept. Fax No.: +98-21-26100356 Direct Tel No.: +98-21-23843563 Please reply to <u>dma@sealeaders.com</u> (Note: This e-mail has been sent as BCC <blind carbon copy to : All R.O.D.-SMC Vessels, to eliminate the lengthy list that would result if this e-mail is printed)

FACSIMILE COMMUNICATION FORM



Port of Fujairah P.O. Box : 787, Fujairah United Arab Emirates Fax : 09-2228851 (Admin.) 09-2228555 (Oprts.) 09-2228312 (Engg.) 09-2228022 (Marine)

مًا + الليجيرر .ب : ١٩٧ - الفجيرة بارات العربية التبعدة من : ٢٢٣٨٥١٥ - • (العدارة) ٢٢٢٨٣٢٥ - (الهندسة) ٢٢٣٨٣٢ - (الهندسة) ٢٢٣٨٢٢ - • (الهندسة)

То:	All Agents / Bunkering Companies / De-Sloping Companies / National Transport Authority / Federal Environment Agency / Hydrographic Office-UK				
Attn:	General Manager / Operations Manager				
From:	Capt. Tamer Masoud – Harbour Master				
Facsimi	le No.: City: Fujairah Country: U.A.E				
Ref. No.	. MD/FAX/18/008 Date: 9 January 2018 No. Pages: 111 + 16Attachmen				

Extracted Notice To Mariner No. 148

(Version 3)

SUBJECT : PORT INFORMATION & REGULATIONS FOR VESSELS CALLING PORT OF FUJAIRAH, OIL TERMINALS, SPMs & ANCHORAGE AREA

As part of our on-going process to improve the Safety & Security standards of vessels calling at Port of Fujairah, Oil Terminals, SPMs & Anchorage Area, we introduce this Revision of our notice to Mariner No. 148 (Version 3) with inclusion of new port developments and regulations.

All Equipment, Mechanical, Electrical Devices & Inert Gas System must be in full working condition and shall maintain readiness status consistent with SOLAS, MARPOL regulations and ISGOTT and OCIMF guidelines.

TABLE OF CONTENTS

	Descri	Description		
I	GENE	RAL INFORMATION	7-34	
	1	Time Zone	7	
	2	Fujairah Port Information	7	
	3	Definitions	7-10	
	4 Email Contacts5 Pilot Stations		10-11	
			11	
		5.1 North Pilot Station	11	
		5.2 South Pilot Station	11	

NM 148 - Version No. 3 / Date : 09/01/2018	Port of Fujairah – Marine Department	Page 1 111

20. Liquid Nitrogen Purging in LPG and LNG Carriers is permitted at Fujairah Offshore Anchorage "D" area with prior approval from Control Tower.

21. Vessels with Security Level 2 or Level 3.

Port Security Officer will board all vessels calling FOAA with security Level 2 or 3 to furnish the DoS with SSO.

Inspection and transportation charges as per Port Tariff.

Vessels with Security Level 2 or Level 3 must leave from FOAA once they finish receiving their services. These vessels are allowed to receive their services (Bunkering, De-slopping, Freshwater, Crew Change, Stores, etc.) for a maximum of 12 hours only.

Following Conditions apply,

- a) Two Patrolling Boats will patrol near the vessel until sailing from FOAA, these Patrolling Boats will be charged as per Port Tariff.
- b) V.H.F Channel 8 should always be on watch for the conversation among the vessel's bridge, patrolling boat and the Control Tower.

22. Restricted Anchoring Adjacent to Fujairah Territorial Waters

Area 1: Between Longitudes 056⁰ 35' E & 056⁰ 49.5' E

Area 2: Between Longitudes 056° 35' E & 056° 47' E

Vessels anchoring adjacent to Fujairah Territorial waters is strictly prohibited.

The coordinates of the areas are given below,

Area 1:

25 ⁰	37.0'	Ν	&	056 ⁰	35'E
25 ⁰	37.0'	N	&	056 ⁰	49.5'E
25 ⁰	24.45'	N	&	056 ⁰	35'E
25 ⁰	24.45'	N	&	056 ⁰	49.5'E

NM 148 - Version No. 3 / Date : 09/01/2018	Port of Fujairah – Marine Department	Page 17 111

Port of Fujairah - Marine Department



<u> </u>					
25 ⁰	19.25'	N	&	056 ⁰	35'E
25 ⁰	19.25'	Ν	&	056 ⁰	47' E
25 ⁰	06.0'	N	&	056 ⁰	35'E
25 [°]	06.0'	Ν	&	056 ⁰	47' E

Mariners please bear in mind that the 'undersea communications cable' is passing adjacent to longitude 056° 49.5' E (please find attached sketch – Attachment # 12).

Free passing of vessels through the aforementioned area is allowed as per International Maritime Law.

23. SPM Channel

There are eight buoys deployed to mark the SPM Channel and their names, position and light characteristics are given below,

Sl.	Buoy Name	Coordinates	Light	Remarks
1.	SPM Channel-Buoy#1	25° 19.4' N & 056° 33.39'E	FLG4S(0.5 Sec ON, 3.5 Sec OFF	Racon (M)
2	SPM Channel-Buoy#2	25° 18.4' N & 056° 33.39'E	FLR4S(0.5 Sec ON, 3.5 Sec OFF	
3	SPM Channel-Buoy#3	25° 19.4' N & 056° 31.10'E	FLG4S(0.5 Sec ON, 3.5 Sec OFF	
4	SPM Channel-Buoy#4	25° 18.4' N & 056° 31.10'E	FLR4S(0.5 Sec ON, 3.5 Sec OFF	
5	SPM Channel-Buoy#5	25° 19.4' N & 056° 28.78'E	FLG4S(0.5 Sec ON, 3.5 Sec OFF	
6	SPM Channel-Buoy#6	25° 18.4' N & 056° 28.78'E	FLR4S(0.5 Sec ON, 3.5 Sec OFF	
7	SPM Channel-Buoy#7	25° 19.4' N & 056° 26.56'E	FLG4S(0.5 Sec ON, 3.5 Sec OFF	· · · · · ·
8	SPM Channel-Buoy#8	25° 18.0' N & 056° 27.00'E	FLR4S(0.5 Sec ON, 3.5 Sec OFF	

Racon (M) is fixed on SPM Channel Buoy # 1.

Crossing or entering the SPM Channel by vessels or utility boats without Port of Fujairah Pilotage is strictly prohibited.

This restricted area is under continuous surveillance and vessels crossing will be recorded in our SPM Channel Monitoring System automatically.

Ship Master / Utility Boat Master crossing or entering without pilotage the SPM Channel by ignoring our regulations will invite a fine of US\$10,000.

NM 148 - Version No. 3 / Date : 09/01/2018	Port of Fujairah – Marine Department	Page 18 111



United Arab Emirates دولة الأمارات الدربية المحدة Government of Shacjah حكومية الشارقية حصومت انتسارهه انتسارهه و Government of Sentress داشرة الموادي البصرية والجمسارية | Deputiment of Sentoris & Customs

To: All Agents/Bunkering Companies/De-slopping Companies/Oil Terminals/Federal Environment Agency/Hydrographic Office - UK

Attn: Operations Manager/Directors

From : Harbour Master , Sharjah port Authority

Ref: HM/MAR/12/147

Date : 27/12/2012

T * d

Notice to Mariners No.101 /2012

Subject: Restricted anchoring and approaching adjacent to Khorfakkan territorial waters between Longitudes 056Deg 36'E and 056 Deg 49.25' E

Please be advised that considering the safety, security and environmental issues, all vessels anchoring adjacent to Khorfakkan Territorial waters (between longitudes 056 Deg 36'E and 056 Deg 49.25'E) is strictly prohibited with immediate effect.

All vessels intending to anchor off Khorfakkan port should contact the Khorfakkan port control on VHF Ch 67/16 and be guided by the port authorities to anchor within 12 Nm (upto Longitude 056 Deg 36'E) of Khorfakkan port.

مريد ٢٠١٠ - ٢٠١ ماري ٢٠٠٠ - ٢٨٢ - ٢٠٠٠ فيران ٢٠٠٠ - ٢٢٠٠ - ٢٠٠٠ Website: www.sharjahports.ac

> 002281334 29 Dec 2012 10:1288 Sherine Ports Marine



United Arab Emirates دولة الامارات المربية المحقية Government of Sharinh حكومة الشارقة والشرة الشوائش اليحسرية والجمسارك 🕴 Customs ، والشرة الشوائش اليحسرية والجمسارك

12-24 NM area bound by following coordinates :

25 Deg 20' N & 056 Deg 36' E 25 Deg 24.75'N & 056 Deg 36'E 25 Deg 24.75' N & 056 Deg 49.25' E 25 Deg 20'N & 056 Deg 49.25'E

Free passing of vessels through the above mentioned area is allowed as per International Maritime Law.

Affected charts : Admiralty chart : BA 3723 and BA 3520

Please advise all your principals and ship masters accordingly.

This order is in force with immediate effect.

Thanks and regards R. Woathi Gom Capt. R.Devathirajan Harbour Master Sharjah port Authorities.

Cc: Chairman, Sharjah port Authorities Cc: Director Administration , Sharjah port Authorities. Cc: Director General, Sharjah ports Cc: Mina Khalid, Hamriyah and Khorfakkan Port control tower. Cc: All department heads Mina Khalid, Hamriyah, Khorfakkan Cc: Coast Guard , Sharjah, Khorfakkan Cc: National Transport authorities.

س ب ۱۰۰۰ الداردة . ارج ب ماند، ۲۰ ما Wobsile: www.sharjahports.ac

Sid

+CE182590

S9 Dec 2012 10:128M Sharjah Ports Marine

	Fort of Parlate	09-2228	, Fujairah mirates		ميتا - القجيرة ص.ب - ۲۸۷ - الفجيرة الإمارات القريبة المتحدة فأكس - ۲۲۲۸۹۱ - ۹ - (الاوارة) د ۲۲۲۸۹۵ - ۹ - (الاهليات) ۲۲۲۸۳۱ - ۹ - (الهندية)		
То:	All Agents / Bunkering Companies / De-Sloping Companies / Oil Terminals Users						
Attn:	General Manager / Operations Manager						
From:	Capt. Ta	amer Masou	d – Harbo	our Maste	r	······································	
Facsimi	le No.:			City:	Fujairah	Country:	U.A.E
Ref. No.	MD/FA	X/18/053	Date:	19 Feb	ruary 2018	No. Pages:	1

FACSIMILE COMMUNICATION FORM

Notice To Mariners No. 240

SUBJECT : RESTRICTED ANCHORING ADJACENT TO U.A.E EAST COAST TERRITORIAL WATERS

Please be advised that anchoring of vessel at **Restricted Area** adjacent to U.A.E East Coast Territorial waters is <u>strictly prohibited</u>. Please refer our Notice to Mariner No. 148 Version 3 & Notice to Mariner No. 101/2012 issued by Khorfakkan Port.

If any vessel is found anchored in the restricted area will invite a permanent entry ban, or a fine of AED 10,000/- or both without further clarification.

Free passing of vessels through the aforementioned area is allowed as per International Maritime Law.

Thanks & Regards,

Capt. Tamer Masoud HARBOUR MASTER

cc : General Manager – PoF CFO – PoF Operations Manager – PoF FOTT Manager - PoF Dy. Harbour Masters - PoF Control Tower. Khorfakkan Port FTA VHFL ADNOC Fujairah Terminal.